



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 6
1445 ROSS AVENUE, SUITE 1200
DALLAS, TX 75202-2733

DATE: 7/5

MEMORANDUM

SUBJECT: Potential Hazardous Waste Site - Site Inspection Report
FROM: O. Thomas Love Jr., Chief
Water Supply Branch (6W-S) *O. Thomas Love Jr.*
TO: Betty Williamson, Chief
SuperFund Management Branch (6H-M)

In response to the CERCLA investigation reports which you recently sent to the Water Supply Branch, I am attaching our comments. Thank you for the opportunity to review these documents.

Attachment:

Site Name: NORANDAL USA
Site Location: JACKSON
Site Number: ARD0004351464

cc: George Pettigrew (6H-E)
Charles Gazda (6E-E)

9679422



INSPECTION REPORT REVIEW
POTENTIAL HAZARDOUS WASTE SITE

SITE NAME : NORANDAL USA, INC. NEWPORT PLANT

LOCATION : JACKSON

SITE NUMBER: ARD006351464

SURVEY DATE: ___/___/___ INSPECTED BY: STATE FIT TAT OTHER: _____

LABORATORY : ___CLP ___EPA ___OTHER_____

RECEIVED FROM: Ed Sierra DATE RECEIVED: 5/23/94

SAMPLE TYPE(s):

SOIL	SURFACE WATER	GROUND WATER	DRINKING WATER
off / on -site	off / on -site	off / on -site	off / on -site

CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological

FOLLOW UP (Y/N):

<u>N</u> (Re)Sampling Requested	<u>N</u> Locate Drinking Water Sources
<u>N</u> Further Action is URGENT	<u>N</u> Keep Site Active ("N"=No Further Action)
	<u>Y</u> Concur with Report Recommendations

SUMMARY:

No Comments.

Concurrence:

Mr McFarrell Davis 6/27/94

Mark E. McCarty
ENGINEER/REVIEWER

6/27/94